

Typical Manual D by others

Grill sizes not calculated or specified. Potential for noisy grills, increased static pressure and reduced airflow.

Triangular mixing boxes cause turbulence in the mixing box which results in poor airflow

Daisy chain mixing boxes: each adds 75 feet of duct length dramatically reducing airflow

Flex trunks likely will not fit through floor system, resulting in constrictions and reduced airflow.

